

## Field Report

---

**Project:** Shepherd of The Hills Lutheran Church

**Report #:** 2

**Project Number:** 17-023

**Date:** 6-27-19






**Weather / Temperature Range:** Sunny, +/- 75

**Time:** 8:00 am


**Report By:** Steve Romatz

---

### Construction Observations:

-  The entire church and fellowship hall structure has been knocked down.
-  Nearly all debris has been removed
-  Masonry and steel have been sorted for recycling
-  Construction sign has been erected
-  West side of site is being kept clean- no debris on neighboring property.

### Work in Progress:

-  Cutting temporary egress door into the east wall at the top of the stairs.

### Verification:

-  N/A

### Photos- Attached Herewith:



**Image #1: New (temporary) egress door is being cut/framed into the east wall at the top of the ramp.**



**Image #2: Existing door opening at top of ramp has been studded shut. This needs to be opened up and a tempdoor must be installed for egress throughout the duration of construction.**



**Image #3: Only a small portion of wall (this was the west wall of the mezzanine stairwell) remains on the west side**



**Image #4: Debris being removed at the southwest corner of the church..**



**Image #5: West side of the site is being kept clean.**



**Image #6: West side of the site is being kept clean**



**Image #7: Only the south corners of the church remain in place.**



**Image #8: Debris removal- looking from the southeast.**



**Image #9: Steel sorted for recycling**



**Image #10: Debris removal- looking from the northeast**