



Project Number:

17-023

Date: 9-5-19

Weather / Temperature Range: Sunny, +/- 75

Time: 1:00 pm

Report By: Steve Romatz

**Construction
Observations:**

- ✚ Structural steel framework has been set for church.
- ✚ Steel deck has been installed at sloped portions of church roof
- ✚ All exterior wood stud walls have been framed and sheathed
- ✚ All interior wood stud wall have been framed
- ✚ Interior HM frame installation has started
- ✚ Exterior wood framed walls have been sheathed
- ✚ Wood buck has been installed @ perimeter of window openings
- ✚ Wood trusses over entry have been set

Work in Progress:

- ✚ Installation of roof sheathing

Verification:

- ✚ N/A

Photos- Attached Herewith:



Image #1: Exterior wall @ previous building exit is now being framed in.



Image #2: Trusses have been set over covered drive area.



Image #3: Roof sheathing is being installed.



Image #4: Hollow metal frames are being set in place.



Image #5: Hollow metal frames are stored directly on concrete- they should have wood blocking under them to avoid rusting.



Image #6: Looking from NW to SE in sanctuary.



Image #7: Steel column bases have been grouted in place.



Image #8: Steel stud wall between green room and sanctuary. Need to cut a door opening in this wall per owner request.



Image #9: Wood truss bearing on the east side of the church.



Image #10: Wood truss bearing on the east side of the church.